In-Production Photo Report for

Leominster Fire Department, MA Job# 38228

Status as of October 20, 2023


In this report your cab completed paint and began initial assembly, the pump house began initial assembly, and the body began the paint process. In the next report the cab and the pump house may continue initial assembly, and the body may continue through paint.

For Valued Customers of









DSC01441



DSC01443



DSC01442



DSC00070



DSC00071




DSC00073



DSC00072



DSC00074



DSC00919



DSC00920



DSC00921 DSC00922



DSC00923





https://allegiancefr.com

ALLEGIANCE TRUCKS*



An Oshkosh Corporation Company