In-Production Photo Report for

Leominster Fire Department, MA Job# 38228

Status as of October 27, 2023

In this report your cab continued initial assembly, the frame build began, the pump house continued initial assembly, and the body continued through paint. In the next report the cab and the pump house may continue initial assembly while the frame build may continue, and the body may continue the paint process.

For Valued Customers of








DSC00160



DSC00162



DSC00161



DSC00216



DSC00217



DSC00219 DSC00220



DSC00218





DSC00221



DSC00086



DSC00222



DSC00087



DSC00088



DSC00995



DSC00089



DSC00996



DSC00997





https://allegiancefr.com

ALLEGIANCE TRUCKS°—



An Oshkosh Corporation Company