In-Production Photo Report for

Leominster Fire Department, MA Job# 38228

Status as of November 03, 2023

In this report your cab continued initial assembly, the frame build continued, the pump house continued initial assembly, and the body completed paint and was staged. In the next report the cab may continue initial assembly, the frame build may continue, the pump house may be staged, and the body may begin initial assembly.


For Valued Customers of







DSC00244



DSC00246



DSC00245



DSC00247



DSC00248



DSC00372



DSC00371



DSC00373



DSC00374



DSC00376



DSC00375



DSC00377



DSC00097



DSC00099



DSC00098



DSC00100



DSC00101



DSC01798



DSC01797



DSC01799







DSC01801





https://allegiancefr.com

ALLEGIANCE TRUCKS*



An Oshkosh Corporation Company