

# In-Production Photo Report for Goffstown Fire Department, NH Job# 39037

Status as of December 22, 2023

In this report the cab was staged, the frame build continued, the pump house completed initial assembly, and the body completed paint. In the next report the cab may remain staged, the frame build may continue, the pump house may remain staged, and the body may begin initial assembly.


**Due to the Pierce Winter/Holiday break, your next report is scheduled for week ending January 6, 2024. Thank you!**



*For Valued Customers of*



POWERED BY  
**ALLEGIANCE**  
TRUCKS®



DSC00188



DSC00189



DSC00190



DSC00225





DSC00226



DSC00227



DSC00228



DSC00229





DSC00250



DSC00251



DSC00252



DSC00253





DSC01100



DSC01101



DSC01102



DSC01103



DSC01104



<https://allegiancefr.com>

POWERED BY  
**ALLEGIANCE**  
— TRUCKS® —



An Oshkosh Corporation Company