

# In-Production Photo Report for Cambridge Fire Department, MA Job# 38010-01

---


Status as of January 12, 2024

In this report the cab was staged to continue initial assembly, the frame build began, the pump house completed initial assembly, and the body completed the paint process. In the next report your cab may remain staged, the frame build may continue, the pump house may remain staged, and the body may begin initial assembly.

*For Valued Customers of*



POWERED BY  
**ALLEGIANCE**  
TRUCKS®




DSC03244



DSC03245



DSC03299



DSC03300






DSC03301



DSC03302



DSC03303



DSC03304





DSC00330



DSC00331



DSC00332



DSC00599





DSC00600



DSC00601



DSC00602



DSC00603



<https://allegiancefr.com>

POWERED BY  
**ALLEGIANCE**  
— TRUCKS® —



An Oshkosh Corporation Company