
In-Production Photo Report for South Portland Fire Department, ME Job# 38003

Status as of January 19, 2024

In this report your cab completed paint and was staged, the pump house structure was fabricated, and the rear body module was fabricated and staged. In the next report the cab may be staged to begin initial assembly, the pump house structure may begin initial assembly, and the body may be staged to begin the paint process.







DSC03303



DSC03305



DSC03304



DSC03306




DSC03307



DSC00037



DSC00036



DSC00031



DSC00032



DSC00034



DSC00033



DSC00035





https://allegiancefr.com

ALLEGIANCE TRUCKS*



An Oshkosh Corporation Company