In-Production Photo Report for South Portland Fire Department, ME Job# 38003 Status as of January 26, 2024

> In this report your cab began initial assembly, the pump house structure was painted, and the rear body module was staged. In the next report the cab may continue initial assembly, the pump house may begin initial assembly, and the body may remain staged to begin the paint process


> > For Valued Customers of Find us on Facebook POWERED BY ALLEGIANCE







DSC00378





DSC00380










38003 Tou

DSC00024





DSC00027





DSC03432







https://allegiancefr.com

ALLEGIANCE _____TRUCKS*____



An Oshkosh Corporation Company