



Photo Album for
Norfolk Fire Department MA

Job # 38464


W/O # 30702958

February 17, 2024

This week the chassis continued with chassis prep, and the pump house was in staging. The body was unavailable for photos in paint. Next week the chassis should continue with chassis prep and the pump house may be mounted. The body should finish with paint.



DSC00455



DSC00456



DSC00457



DSC00458



DSC00459



DSC00460



DSC00461



DSC00462



DSC00463



DSC00464



DSC00465



DSC00466