In-Production Photo Report for

Plaistow Fire Department, NH Job# 38805

Status as of March 22, 2024

In this report the cab completed paint and was staged, while the front and rear body modules began fabrication. In the next report your cab may begin initial assembly, while the body modules may complete fabrication and release to paint.

For Valued Customers of









DSC00505



DSC00507



DSC00506



DSC03019



DSC03020



DSC03014



DSC03021



DSC03015



DSC03016



DSC03018



DSC03017





https://allegiancefr.com

ALLEGIANCE TRUCKS*



An Oshkosh Corporation Company