In-Production Photo Report for

Belchertown Fire Department, MA Job# 38225

Status as of April 25, 2024


In this report your cab completed initial assembly, the pump house structure was fabricated, and the rear body module completed fabrication. In the next report your cab may be staged, and the pump house structure and rear body module may remain staged.

For Valued Customers of









DSC00007



DSC00009



DSC00008




DSC00010



DSC00011



DSC03123



DSC03122



DSC03124



DSC03445



DSC03447



DSC03446



DSC03448



DSC03449





https://allegiancefr.com

ALLEGIANCE TRUCKS*



An Oshkosh Corporation Company