



# Photo Album for Campton / Thornton FD., NH

Job # 38636

W/O # 30876994

April 20, 2024

This week the chassis was in staging (no photos) and the pump house began final pump assembly. The body was fabricated. Next week the chassis should be in staging and the pump house should finish final pump assembly. The body may begin the paint process.



DSC00051



DSC00052




DSC00053



DSC00054



DSC00055



DSC00056



DSC00057



DSC00341



DSC00342



DSC00343



DSC00344