



Photo Album for Campton / Thornton FD., NH

Job # 38636


W/O # 30876994

April 27, 2024

This week the chassis was in staging (no photos) and the pump house was in staging. The body began the paint process. Next week the chassis should be in staging and the pump house should be in staging. The body should continue the paint process. .



DSC00267



DSC00268



DSC00269



DSC00270



DSC00271