



# Photo Album for Campton / Thornton FD., NH

Job # 38636

W/O # 30876994

May 4, 2024

This week the chassis began preparations for fire service and the pump house was in staging (no photos). The body continued the paint process. Next week the chassis should continue with chassis prep and the pump house may be mounted. The body should finish with paint



DSC00229



DSC00230



DSC00231



DSC00232



DSC00305



DSC00306



DSC00307



DSC00308