In-Production Photo Report for Merrimack Fire Department, NH Job# 38808

Status as of April 25, 2024

In this report your cab remained staged, the pump house completed initial assembly, the torque box, front body module remained staged, and the rear body module completed paint. In the next report your cab, pump house, torque box, and front body module may remain staged, and the rear body module may begin initial assembly.







DSC00004



DSC00006



DSC00005



DSC00104



DSC00105



DSC03194



DSC00106



DSC03195



DSC03489



DSC03491



DSC03490



DSC00731



DSC00732



DSC00734



DSC00733



DSC00735





https://allegiancefr.com

ALLEGIANCE TRUCKS*



An Oshkosh Corporation Company