

In-Production Photo Report for Plaistow Fire Department, NH Job# 38805

Status as of April 12, 2024


In this report the cab and pump house were installed on the frame, the torque box remained staged, the front body module completed paint, and the rear body module began the paint process. In the next report your chassis may be staged, the torque box may begin initial assembly, the front body module may remain staged, and the rear body module may continue through paint.



For Valued Customers of



POWERED BY
ALLEGIANCE
TRUCKS®




DSC00001



DSC00002




DSC00003



DSC00004



DSC00005



DSC00006



DSC00007



DSC00008



DSC00009



DSC00010



DSC00011



DSC00012



DSC00013



DSC00014



DSC00015



DSC00016



DSC00017



DSC00018



DSC00019



DSC00020



DSC00021




DSC00022



DSC00023



DSC00024



DSC00025



DSC00026



DSC00027



DSC00028



DSC00029



DSC00030



DSC00031




DSC00032




DSC00033



DSC00034



DSC00035



DSC00036



DSC00037



DSC00038



DSC00039



DSC00040



DSC00041



DSC00042



DSC00043



DSC00044



DSC00045



DSC00046



DSC00047




DSC00048



DSC00049




DSC00050




DSC00051



DSC00052



DSC00053



DSC00054



DSC00055



DSC00056



DSC00057



DSC00058



DSC00059



DSC00060



DSC00061



DSC00062



DSC00063



DSC00064



DSC00065



DSC00066



DSC00067



DSC00068



DSC00185



DSC00186



DSC00187



DSC00188



DSC00189




DSC03280



DSC03281



DSC03282



DSC00854



DSC00855



DSC00856



DSC00857



DSC00858



<https://allegiancefr.com>

POWERED BY
ALLEGIANCE
— TRUCKS® —



An Oshkosh Corporation Company