

# In-Production Photo Report for Plymouth Fire Department, NH Job# 38693


Status as of April 05, 2024

In this report your cab completed fabrication and began the paint process while the pump house structure was fabricated. In the next report your cab may continue through paint while the pump house structure may remain staged.



POWERED BY  
**ALLEGIANCE**  
TRUCKS®

*For Valued Customers of*



DSC00396



DSC00397



DSC00398



DSC00073





DSC00074



DSC00075



<https://allegiancefr.com>

POWERED BY  
**ALLEGIANCE**  
— TRUCKS® —



An Oshkosh Corporation Company