In-Production Photo Report for Plymouth Fire Department, NH Job# 38693 Status as of April 19, 2024

> In this report your cab completed the paint process, the pump house structure remained staged, and the body was fabricated and staged. In the next report your cab may remain staged to begin initial assembly, the pump house structure may remain staged, and the body may remain staged to begin the paint process.

> > For Valued Customers of





DSC00327





DSC00325






DSC00326

DSC



DSC00087



DSC03226



DSC03227



DSC03228



DSC03229



DSC03230





https://allegiancefr.com



An Oshkosh Corporation Company