In-Production Photo Report for

Plymouth Fire Department, NH Job# 38693


Status as of April 25, 2024

In this report your cab began initial assembly, the pump house began initial assembly, and the body remained staged to begin the paint process. In the next report your cab continue initial assembly, the pump house may continue initial assembly, and the body may begin the paint process.

For Valued Customers of







DSC00056



DSC00058



DSC00057



DSC00059



DSC00060



DSC03151



DSC03150



DSC03152



DSC03153



DSC03419



DSC03154



DSC03420



DSC03421



DSC03423



DSC03422





https://allegiancefr.com

ALLEGIANCE TRUCKS*



An Oshkosh Corporation Company