

In-Production Photo Report for Brockton Fire Department, MA Job# 38747

Status as of May 31, 2024


In this report your cab was installed on the frame while assembly continued, the transverse compartment remained staged, the pump house was staged to begin the paint process, and the body completed paint and began initial assembly. In the next report your chassis and transverse compartment may remain staged, the pump house may be painted, and the body may continue initial assembly.



For Valued Customers of



POWERED BY
ALLEGIANCE
TRUCKS®




DSC00015



DSC00016



DSC00017



DSC00018




DSC00019



DSC00020



DSC00021



DSC00022



DSC00023



DSC00024



DSC00025



DSC00026



DSC00027



DSC00028



DSC00029



DSC00030



DSC00031



DSC00032



DSC00033



DSC00034



DSC00035



DSC00036



DSC00037



DSC00038



DSC00039



DSC00040



DSC00041



DSC00042



DSC00043




DSC00044



DSC00045



DSC00046



DSC00047



DSC00048



DSC00049




DSC00050



DSC00051



DSC00052



DSC00053



DSC00054



DSC00055



DSC00056



DSC00057



DSC00058



DSC00059



DSC00060



DSC00061



DSC00062



DSC00063



DSC00064



DSC00065



DSC00066



DSC00067



DSC00068



DSC00069



DSC00070



DSC00071




DSC00072



DSC00073



DSC00074



DSC03027



DSC03028



DSC03029



DSC03674



DSC03675



DSC03676



DSC03677



DSC03678



DSC03607



DSC03608



DSC03609



DSC03610



DSC03611



<https://allegiancefr.com>

POWERED BY
ALLEGIANCE
— TRUCKS® —



An Oshkosh Corporation Company