In-Production Photo Report for

New Bedford Fire Department, MA Job# 38803

Status as of May 10, 2024

In this report the tractor cab began fabrication while the tiller cab continued fabrication. In the next report the tractor cab may continue fabrication while the tiller cab may complete the fabrication process and release to paint.

For Valued Customers of









DSC00258



DSC00260



DSC00259



DSC00261



DSC00262



DSC00269



DSC00268



DSC00270





https://allegiancefr.com

ALLEGIANCE TRUCKS*



An Oshkosh Corporation Company