In-Production Photo Report for


New Bedford Fire Department, MA Job# 38803

Status as of July 19, 2024

In this report your apparatus continued final assembly while the tiller cab completed initial assembly and was staged. In the next report the tiller cab may be merged, and final assembly may continue.







DSC03992



DSC03994



DSC03993



DSC03995



DSC03996



DSC03998



DSC03997



DSC03999



DSC04000



DSC04002



DSC04001



DSC04003



DSC04004



DSC04006



DSC04005



DSC04007





https://allegiancefr.com





An Oshkosh Corporation Company